

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A D 0 8 6 0 1	Manifest No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address DOUGLAS AIRCRAFT CO 190th & Normandie Torrance, CA 90502		A. State Manifest Document Number 84351240		B. State Generator's ID	
4. Generator's Phone () (213) 533-6677		C. State Transporter's ID 35665		D. Transporter's Phone (213) 268-3137	
5. Transporter 1 Company Name J. C. Liquid Waste Disposal		6. US EPA ID Number C A D 0 5 8 0 1 8 3 6 7		E. State Transporter's ID	
7. Transporter 2 Company Name		8. US EPA ID Number		F. Transporter's Phone	
9. Designated Facility Name and Site Address Casmalia P.O. Box E. NTU Road Casmalia, CA 93429		10. US EPA ID Number C A D 0 2 0 7 4 8 1 2 5		G. State Facility's ID C A D 0 2 0 7 4 8 1 2 5	
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol
a. Waste Sodium Hydroxide Solution - Corrosive UN1824		001	ET	04500	G
b.					
c.					
d.					
J. Additional Descriptions for Materials Listed Above Sodium Hydroxide 8% 6% Sodium Aluminate 6% 4% Sulfur 6% 4% Water 80% 86%		K. Handling Codes for Wastes Listed Above 08/4			
15. Special Handling Instructions and Additional Information #60 Use gloves, goggles, respirator - May cause severe burns to skin and eyes.					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.					
Printed/Typed Name Donald C. Gerber		Signature <i>Donald C. Gerber</i>		Date Month Day Year 02 13 85	
17. Transporter 1 Acknowledgement of Receipt of Materials		Signature <i>Santos Ybarra</i>		Date Month Day Year 02 13 85	
Printed/Typed Name SANTOS YBARRA W/6 51810		Signature <i>Joe Serrani</i>		Date Month Day Year 02 14 85	
18. Transporter 2 Acknowledgement or Receipt of Materials		Signature <i>Joe Serrani</i>		Date Month Day Year 02 14 85	
Printed/Typed Name JOE SERRANI W/6 51810		Signature <i>Joe Serrani</i>		Date Month Day Year 02 14 85	
19. Discrepancy Indication Space					
20. Facility Owner or Operator: Certification of receipt of materials covered by this manifest except as noted in Item 19. #40273-31, 220/65					
Printed/Typed Name Casmalia Resource		Signature <i>Carol Schindler</i>		Date Month Day Year 05 14 85	

SCANNED

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A D 0 8 6 5 1 0 0 0 5	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address DOUGLAS AIRCRAFT CO. 190th & Normandie Torrance, CA 90502			A. State Manifest Document Number 84351240			
4. Generator's Phone (90502) (213) 533-6677			B. State Generator's ID			
5. Transporter 1 Company Name J. C. Liquid Waste Disposal			6. US EPA ID Number C A D 0 5 8 0 1 8 3 6 7		C. State Transporter's ID	
7. Transporter 2 Company Name			8. US EPA ID Number		D. Transporter's Phone (213) 268-3137	
9. Designated Facility Name and Site Address Casmalia P.O. Box 8. NTU Road Casmalia, CA 93429			10. US EPA ID Number C A D 0 2 0 7 4 8 1 2 5		E. State Transporter's ID	
					F. Transporter's Phone	
					G. State Facility's ID	
					H. Facility's Phone	
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)			12. Containers	13. Total Quantity	14. Unit Wt/Vol	1. Waste No.
a. Waste Sodium Hydroxide Solution - Corrosive UN1824			No. 001	Type ET	04500G	121
b.						
c.						
d.						
J. Additional Descriptions for Materials Listed Above			K. Handling Codes for Wastes Listed Above			
Sodium Hydroxide 6X 6X						
Sodium Aluminate 6X 4X						
Sulfur 6X 4X						
Batteries 80X 80X						
15. Special Handling Instructions and Additional Information #60						
Use gloves, goggles, respirator - May cause severe burns to skin and eyes.						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.						
Printed/Typed Name Donald C. Gerber			Signature <i>Donald C. Gerber</i>		Date Month Day Year 02 13 85	
17. Transporter 1 Acknowledgement of Receipt of Materials			Signature <i>John J. ...</i>		Date Month Day Year 02 13 85	
18. Transporter 2 Acknowledgement or Receipt of Materials			Signature		Date Month Day Year	
Printed/Typed Name			Signature		Date Month Day Year	
19. Discrepancy Indication Space SCANNED						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.						
Printed/Typed Name			Signature		Date Month Day Year	

SCANNED